

134-130 2008-18 Ski-Doo 600 H.O./SDI/E-tec/RS Y-pipe (High Temp Black)

Installation Instructions

Remove stock y pipe; be sure to keep all stock springs.

Be sure the Straightline y-pipe has no manufacture defects. If the pipe has been run/used there are **no warrantees** for fitment.

Jetting Requirements

There are no fuel programming changes needed to run the SPI Y-pipe.

Clutching - Straightline recommends adding an Adjustable Pin kit to your snowmobile to help enhance the power.

Kits are available from Straightline or your local Ski-doo dealer.

Straightline Performance 15250 Hornsby St Forest Lake, MN 55025 651-466-0212 www.straightlineperformance.com

Technical questions please email tech@straightlineperformance.com



Facebook @ straightlineperformanceinc1
Youtube @ straightlineperfinc
Twitter @ straightlineperf